



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Repair Luminaires

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Electrician

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

safety glasses, safety footwear, test meter, *ladder, asbestos respirator if required, class zero gloves*

WESTERN HAZARD CATEGORY*

Energy/WorkSite Hazards

HAZARD TYPE*

Electricity/Working at Heights, Sharp Objects

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Dave Ostrom

REVIEWED BY:

Electrical/Controls Shop

MGMT APPROVAL:

Ken Gee

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Assess Work Site	Slip, trip, fall from height	WP-41, check for asbestos, ladder safety training
Isolate electrical power	Shock	Lock-out tag-out
Remove lens and lamps	Fall from height, cuts, glass breakage	Ladder safety training, gloves
Remove ballast cover	PCB if ballast is old and leaking	Follow PCB ballast procedure S-12 when required
Test for electrical potential	Shock	Test meter, class zero gloves
Replace ballast	Fall from height, cuts, glass breakage	Ladder safety training, gloves
Replace ballast cover	Fall from height, cuts, glass breakage	Ladder safety training, gloves
Replace lamps and lens	Fall from height, cuts, glass breakage	Ladder safety training, gloves
Turn on electrical power		