



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Asbestos Ceiling Tile Removal

WESTERN HAZARD CATEGORY*

Chemical Hazard

DATE:

June 29, 2006

DEPARTMENT

CCPS

HAZARD TYPE*

Carcinogen

WRITTEN BY:

Steve Clemens

WESTERN JOB CLASSIFICATION*

Fire Safety Staff

LOSS POTENTIAL RATING*

Moderate

REVIEWED BY:

Steve Clemens

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Safety Shoes

*refer to Stantec Specific Job Report

MGMT APPROVAL:

SEQUENCE OF TASK

POTENTIAL HAZARDS

ACTION OR PROCEDURE

In close work area as Type 2 procedure	Asbestos Dust	Shut off mechanical equipment or seal off openings before starting.
Remove Tile	Trip hazard in corridor	Keep work areas neat and to one side at a time in corridors.
Double bag tile	positive or negative pressure damaging your tarped area.	Wear proper PPD
Vacuum area		Notify occupants of work area
Dispose of tile		Work with proper procedures of Type 2 removal.