



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Inspections of fume cabinets

DEPARTMENT

CCPS

WESTERN JOB CLASSIFICATION*

Fire Safety Staff

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Grade 1 safety footwear, safety glasses (eye protection)

WESTERN HAZARD CATEGORY*

Worksite/ Chemical Hazards

HAZARD TYPE*

Slips.Trips.Falls, Protruding/Sharp Objects, Pinch Points/ All Chemical Hazards

LOSS POTENTIAL RATING*

Moderate/ Low

*refer to Stantec Specific Job Report

DATE:

June 29, 2006

WRITTEN BY:

Steve Clemens

REVIEWED BY:

Steve Clemens

MGMT APPROVAL:

SEQUENCE OF TASK

POTENTIAL HAZARDS

ACTION OR PROCEDURE

| SEQUENCE OF TASK | POTENTIAL HAZARDS | ACTION OR PROCEDURE |
|--|--|-------------------------------|
| Inform occupants | Cuts (broken glass) | PPE, comply with lab safety |
| Ensure no chemical/ R.I./ Fire hazards | Chemical exposure, fire, struck by/against | Ensure WHMIS. O.F.C. training |
| Ensure clean work area | Pinch Point | |
| | Fall, puncture | |
| | | |
| | | |
| | | |
| | | |
| | | |