



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Power Hands Tools

DEPARTMENT

CCPS

WESTERN JOB CLASSIFICATION*

Fire Safety Staff

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Hearing protection, required clothing, grade 1 safety footwear, safety glasses/goggles

WESTERN HAZARD CATEGORY*

Equipment Hazards

HAZARD TYPE*

Power Tools

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

June 29, 2006

WRITTEN BY:

Steve Clemens

REVIEWED BY:

Steve Clemens

MGMT APPROVAL:

SEQUENCE OF TASK

POTENTIAL HAZARDS

ACTION OR PROCEDURE

1. Inspect power tool completely before plugging in to power source.	1. Changing blades & bits	1. Wear PPE
2. If changing bits or blades - make sure you unplug power tool		
3. Survey area that you are cutting or drilling into.		
4. Make sure power source (outlet or extension cord) is properly grounded and on safe surroundings.		
5. When power tool in no longer needed, unplug and move out of work area.		
6. When changing blades or bits - test power tool to insure proper installation		
Inspect tool/cord, to ensure safe	Projectile, burn, sharp material	PPE, anti - vibe gloves (I.R.)
Read operating instructions (If necessary)	struck by/against, vibration, R.S.I. position	Protect from damage, use G.F.C.I. (I.R.) If unsafe.
Replace attachments as required	Noise	TAG/ Ensure repair or replacement
Grip firmly for use		Use by manufacturer's intructions
Maintain in good condition		
*Drill, Sawzall, Jigsaw, Die Grinder, Mini-grinder, etc.	**I.R. if required	