



Western

# JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

**WORKPLACE TASK TO BE ANALYSED**

Asbestos Ceiling Tile Removal

**DEPARTMENT**

Facilities Management

**WESTERN JOB CLASSIFICATION\***

Carpenters

**REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT**

white Tyvek suit, respirator, HEPA vacuum

**WESTERN HAZARD CATEGORY\***

Chemical Hazards

**HAZARD TYPE\***

Carcinogen

**LOSS POTENTIAL RATING\***

Moderate

\*refer to Stantec Specific Job Report

**DATE:**

March 17, 2021

**WRITTEN BY:**

Ted Chelchowski

**REVIEWED BY:**

Structural Shop

**MGMT APPROVAL:**

Ted Chelchowski

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Create a shutdown (for Dental Sciences, Social Science)	Asbestos dust into ductwork if not shut down	
In close work area as Type 2 procedure ( <i>see WP-11</i> )	Asbestos dust	Shut off mechanical equipment or seal off openings before starting
Remove tile	Trip hazard in corridor	Keep work areas neat and to one side at a time in corridors
Double bag tile		Wear proper PPE
Vacuum area		Notify occupants of work area
Dispose of tile		Work with proper procedures of Type 2 removal