



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Hanging Articles

WESTERN HAZARD CATEGORY*

WorkSite/Ergonomic/Tool Hazards

DATE:

May 30, 2017

DEPARTMENT

Facilities Management

HAZARD TYPE*

Working at Heights/Overuse, Overloading/ Power Tools

WRITTEN BY:

Ted Chelchowski

WESTERN JOB CLASSIFICATION*

Carpenters

LOSS POTENTIAL RATING*

Moderate

REVIEWED BY:

Structural Shop

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Safety glasses, safety footwear, hearing protection, dust mask (I.R.)

*refer to Stantec Specific Job Report

MGMT APPROVAL:

Ted Chelchowski

SEQUENCE OF TASK

POTENTIAL HAZARDS

ACTION OR PROCEDURE

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Securing articles to walls	Overlifting Burns (drill bit)	Wear PPE
Lifting articles	Eyes	Survey wall before drilling
Drilling holes to fasten articles	Ears Slivers & cuts	Use ladder safety
Using ladder when necessary	Falling	When impossible to move, check furniture if secure and stable, otherwise use ladder or scaffold
Standing on existing furniture while fastening articles		Request assistance when needed
Installing fasteners		