



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Fume Hood Maintenance

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Controls Mechanic

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Safety glasses, safety footwear, gloves

WESTERN HAZARD CATEGORY*

Energy/Chemical Hazards

HAZARD TYPE*

Electricity/All chemical

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Doug Johnson

REVIEWED BY:

Electrical/Controls Shop

MGMT APPROVAL:

Ken Gee

SEQUENCE OF TASK

POTENTIAL HAZARDS

ACTION OR PROCEDURE

Enter space to check fume hood status	Check door posting for hazards	Lab safety procedure
User remove any hazards in work area	Check door posting for hazards	Lab safety procedure
Check fume hood control	Ladder, position, elect. shock, asbestos	Ladder, Lock-Out
Repair and replace as required		