



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Install & Repair Electrical Devices & Equipment

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Controls Mechanic

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Safety glasses, safety footwear, lock-out tag-out tags and lock, rubber gloves, test meter

WESTERN HAZARD CATEGORY*

Energy Hazards

HAZARD TYPE*

Electricity

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Doug Johnson

REVIEWED BY:

Electrical/Controls Shop

MGMT APPROVAL:

Ken Gee

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Isolate electrical circuit	Electrical shock	Lock-out/Tag-out
Test electrical circuit with tester	Electrical shock	Wear safety gloves test meter
Remove defective device or equipment		
Install new device or equipment		
Remove lock		
Re-energize circuit		