



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Maintain Air Compressors

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Controls Mechanic

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Safety glasses, safety footwear, gloves

WESTERN HAZARD CATEGORY*

WorkSite Hazards

HAZARD TYPE*

Pinch points, struck by

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Doug Johnson

REVIEWED BY:

Electrical/Controls Shop

MGMT APPROVAL:

Ken Gee

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Isolate from power	Auto start	Lock-Out Tag-Out
Check belts	Pinch, abrasions	Gloves
Check oil		
Change oil and belts as required	Pinch, stike against, slips	Rags, oil dry, gloves
Check cycle time of compressor		