



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Pull Pneumatic Lines in Conduit

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Controls Mechanic

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Safety glasses, safety footwear, gloves

WESTERN HAZARD CATEGORY*

Ergonomic/Worksite Hazard

HAZARD TYPE*

Awkward posture, Strain, Working at Heights

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Doug Johnson

REVIEWED BY:

Electrical/Controls Shop

MGMT APPROVAL:

Ken Gee

| SEQUENCE OF TASK | POTENTIAL HAZARDS | ACTION OR PROCEDURE |
|------------------------------------|--------------------------|-----------------------------------|
| Feed fish into conduit | Ladder, position | Ladder safety |
| Attach pneumatic line to fish tape | Ladder, position, strain | Ladder safety, use wire lubricant |
| Pull pneumatic line into conduit | | |
| Remove wire from fish tape | | |
| Rewind fish tape | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |