



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Troubleshoot Pneumatic Controls

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Controls Mechanic

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

Safety glasses, safety footwear, gloves

WESTERN HAZARD CATEGORY*

Energy/WorkSite Hazards

HAZARD TYPE*

Electricity, Steam/Working at Heights

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Doug Johnson

REVIEWED BY:

Electrical/Controls Shop

MGMT APPROVAL:

Ken Gee

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Check system for air leaks	Ladder, position	Ladder safety
Check for faulty components		Asbestos procedures
Repair/replace as required	Hot steam lines	Gloves
Check electrical interface	Shock	Isolate power where possible