



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Install & Repair Electrical Devices & Equipment

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Electrician

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

safety glasses, safety footwear, lock-out tag-out tags and lock, rubber gloves, test meter, **Ladder**

WESTERN HAZARD CATEGORY*

Energy Hazard

HAZARD TYPE*

Electricity

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Dave Ostrom

REVIEWED BY:

Electrical/Controls Shop

MGMT APPROVAL:

Ken Gee

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Assess Work Site	Slip, trip, fall from height	WP-41, Ladder safety training
Isolate electrical circuit	Electrical shock	Lock-Out/Tag-Out
Test electrical circuit with tester	Electrical shock	Wear safety gloves test meter
Remove defective device or equipment		
Install new device or equipment		
Remove lock		
Re-energize circuit		