



Western

JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

WORKPLACE TASK TO BE ANALYSED

Pull Wire

DEPARTMENT

Facilities Management

WESTERN JOB CLASSIFICATION*

Electrician

REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT

safety glasses, safety footwear, **class zero** gloves, asbestos mask and coveralls, **ladder, nylon fish tape, steal fish tape**

WESTERN HAZARD CATEGORY*

Energy/Worksite Hazards

HAZARD TYPE*

Electricity/Working at Heights, Slips/Trips/Falls

LOSS POTENTIAL RATING*

Moderate

*refer to Stantec Specific Job Report

DATE:

March 17, 2021

WRITTEN BY:

Dave Ostrom

REVIEWED BY:

Electrical/Controls Shop

MGMT APPROVAL:

Ken Gee

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Assess Work Site	Slip, trip, fall from height	WP-41, laddersafety training
Protect fish tape from contact with live electrical equipment	Shock, arc flash	Isolate live contact points, Lock Out Tag Out, class zero gloves, insulating materials
Feed fish into conduit	Ladder, position, asbestos, shock	Ladder safety, asbestos procedures, class zero gloves
Attach wire to fish tape	Ladder, position, strain	Ladder safety, use wire lubricant
Pull wire into conduit	Shock, arc flash	Isolate live contact points, Lock Out Tag Out, class zero gloves, insulating materials
Remove wire from fish tape		
Rewind fish tape		
		WP- for Live work policy with PPD Safety Committee