



Western

# JOB HAZARD ANALYSIS - Task Specific

NEW

REVISED

**WORKPLACE TASK TO BE ANALYSED**

Service/Maintenance/Repair of Fume Cabinets

**DEPARTMENT**

Facilities Management

**WESTERN JOB CLASSIFICATION\***

Mechanical Trades (All)

**REQUIRED EQUIPMENT AND/OR PERSONAL PROTECTIVE EQUIPMENT**

Grade 1 safety footwear, protective clothing, gloves, safety glasses/goggles, knee pads

**WESTERN HAZARD CATEGORY\***

WorkSite hazards

**HAZARD TYPE\***

Fire//Explosion, Slips/Trips/Falls

**LOSS POTENTIAL RATING\***

Moderate

\*refer to Stantec Specific Job Report

**DATE:**

March 17, 2021

**WRITTEN BY:**

Ken Hill

**REVIEWED BY:**

ACMF Shop

**MGMT APPROVAL:**

Ken Hill

SEQUENCE OF TASK	POTENTIAL HAZARDS	ACTION OR PROCEDURE
Inform occupants	Cuts (broken glass)	PPE, comply with lab safety
Ensure no chemical/fire hazards/broken glass (by occupant)	Chemical exposure, fire,	Work above bench policy, WHMIS. O.F.C.
Ensure clean work area	Struck by/against	Work by trained licensed trades
Shut down cabinet,lockout/tagout (I.R.)	Pinch point ,fall	
Perform task	Puncture	
Clean up material/area	Infectious deseases	
*Comply with Reg 278/05 If ACM present		O.F.C.-Ontario Fire Code